

STEP File Finder

ZSS 26 Stepper Motor

Download by mouse click



ZSS 26

without 2nd shaft

with 2nd shaft

without gear

GPL 22 1-stage
4:1 5:1 7:1

GPL 22 2-stage
16:1 28:1 49:1
20:1 35:1

GPL 22 3-stage
64:1 112:1 196:1
80:1 140:1 245:1

GPL 26 1-stage
3.5:1 6:1
4.33:1 7.67:1

GPL 26 2-stage
12.25:1 26:1 46:1
18.78:1 33.22:1

GPL 26 3-stage
81.37:1 143.96:1 276:1
112.67:1 199.33:1

without gear

GPL 22 1-stage
4:1 5:1 7:1

GPL 22 2-stage
16:1 28:1 49:1
20:1 35:1

GPL 22 3-stage
64:1 112:1 196:1
80:1 140:1 245:1

GPL 26 1-stage
3.5:1 6:1
4.33:1 7.67:1

GPL 26 2-stage
12.25:1 26:1 46:1
18.78:1 33.22:1

GPL 26 3-stage
81.37:1 143.96:1 276:1
112.67:1 199.33:1

Cable Output

radial

axial

